



DEPARTMENT OF  
WATER RESOURCES

# BUTTE CREEK *Fact Sheet* Site 0.8

## Emergency Levee Repairs Summer 2007

### Location

River: Butte Creek

River Mile: 0.8

Longitude/Latitude:

N39.689187

W-121.777197

Nearest City: Chico

County: Butte

Bank: Left



### Length of Repair


40 Feet\*

### Repair Type

Riprap  
(rock armor)

### Lead Agency

Department  
of Water  
Resources



\* Length of repair may change.

**For further information,  
please contact:**

**Elizabeth Scott**  
**DWR Public Affairs Office**  
**(916) 835-5344**  
**[leveerepair@water.ca.gov](mailto:leveerepair@water.ca.gov)**

DEPARTMENT OF WATER RESOURCES  
PO Box 942836, Sacramento, CA 94236

**[www.levees.water.ca.gov](http://www.levees.water.ca.gov)**

